



October 24, 2006

Mr. Alex Kerner
Tri Star Technologies
2201 Rosecrans Ave.
El Segundo, CA 90245

Subject: Boeing Fort Walton Beach M100L Laser Wire Marker

Mr. Kerner,

I would like to take time and thank you for the delivery of our new M100L Laser Wire Marker. My technicians and I are extremely satisfied with your product, especially the clarity and quality of the marking on the wire. This unit with out a doubt meets our Boeing 5152 wire identification specification. I was also very pleased with your engineer's installation, operator and maintenance training of our technicians. The technicians commented on how user friendly and the ease of operation. I also like how compact the unit is and requires little space. The technicians were also impressed with how easy it is to maintain. The technicians were using the unit right after your engineer provided their training. I would like to thank you again for your product and your outstanding support.

Sincerely,

Michael W. Estes
The Boeing Company
SOF Support Systems / Repair Center
626 Anchors Street NW
Mail Code 7201-9001
Fort Walton Beach, FL 32548